






Rosettenkappe 815.90.E0160

- Ersatzteil für alle Rosetten der Artikel 815.21.10060, 815.21.20060, 815.20.10065, 815.21.30060, 815.21.31060, 815.90.01060, 815.90.02060, 815.09.11060, 815.09.30060, 815.06.11065, 815.04.11065, 815.03.12065, 815.30.11060
- Edelstahl, Schwarz matt pulverbeschichtet



Abmessungen in mm



Oberfläche/Material

DC

Alternative Oberfläche/Material

Chr

Technische Änderungen vorbehalten, 21.06.2021

HEWI Heinrich Wilke GmbH
Postfach 1260
D-34442 Bad Arolsen

Telefon: +49 5691 82-0
Telefax: +49 5691 82-319

info@hewi.de
www.hewi.com



Web: www.unidomo.de

Telefon: 04621- 30 60 89 0

Mail: info@unidomo.com

Öffnungszeiten: Mo.-Fr. 8:00-17:00 Uhr

VIESSMANN



 **Vaillant**

WOLF

 **JUNKERS**  **BOSCH**

 **remeha**

 **DAIKIN**

ROTEX
a member of DAIKIN group



Individuelle Beratung



Kostenloser Versand



Hochwertige Produkte



Komplettpakete



Über 15 Jahre Erfahrung



Markenhersteller