

Parçalar / Náhradní díly / Náhradné diely /
ти / Części Zapasowe / Pieśe de schimb /
Reservni delovi / Резервни делови /
vad varuosad / Резервју дају

This exploded view diagram illustrates the assembly of a washing machine door. The components are numbered as follows:

- 1:** Hinge pins and hinge brackets.
- 2:** Door gasket (seal) and its retaining clips.
- 3:** The main door panel.
- 4:** Various screws and bolts used for assembly.
- 5:** Locking mechanism components, including the lock body and bolt.
- 6:** Spacers or washers for the locking mechanism.
- 7:** The door latch assembly.
- 8:** The door handle assembly.
- 9:** The door hinge support bracket.
- 10:** The door hinge support plate.
- 11:** The door hinge support cap.
- 12:** The door hinge support plate (alternative view).
- 13:** The door hinge support cap (alternative view).
- 14:** The door hinge support cap (alternative view).
- 15:** The door hinge support cap (alternative view).
- 16:** The door hinge support cap (alternative view).

The diagram includes a note "Hole downward" pointing to the door hinge support cap (11) and a red 'X' mark indicating a specific assembly point. A dashed box highlights the door hinge support cap (11) and its associated components.



1220 / A 868 640



www.idealstandardinternational.com





Web: www.unidomo.de

Telefon: 04621- 30 60 89 0

Mail: info@unidomo.com

Öffnungszeiten: Mo.-Fr. 8:00-17:00 Uhr

VIESSMANN



 **Vaillant**

WOLF

 **JUNKERS**  **BOSCH**

 **remeha**





 **DAIKIN**

ROTEX
a member of DAIKIN group







-  Individuelle Beratung
-  Kostenloser Versand
-  Hochwertige Produkte

-  Komplettpakete
-  Über 15 Jahre Erfahrung
-  Markenhersteller



			0	1	2	3	4	5	6	7	8	9
			°C	°C	°C	°C	°C	°C	°C	°C	°C	°C
0,3 MPa	50°C	16°C	49,5	49,5	48	46	42,5	41	37	33,5	31	28
3 bar	65°C	16°C	65	65	63,5	60,5	57	53,5	49	44,5	39	34,5
	81°C	16°C	81	81	78,5	73	69	63,5	56	49	42,5	36



	P	bar		MAX. 10		5			Q
			0,5					(3 bar)	
	T	°C		MAX. 80		65			I/min
						40			23